



European Club of ICOLD
Working group on Levees and Flood Defences
EUCOLD LFD WG



Lessons learned from levee incidents and failures of German case studies

Working Group Meeting, 5th September 2023, Interlaken

M. Sc. Burcu Ersoy, M. Sc. Lucas Werner, Dr.-Ing. Ronald Haselsteiner

Outline

Introduction

General aspects

German conditions

Selected German case studies – lessons learned

Conclusion

Introduction

Flood frequency and damages during the last decades in Germany

Old town of Cologne 1995 with view on the dome, Source: StEB Köln



Monestry Weltenburg during Danube flood 1999, Quelle: Bayerisches LfU



Flood on Mulde River 2002 at Weesenstein, Source: www.si-journal.de



Flood 2021 on the River Erft, City Erftstadt Blessem, Source: www.rnd.de



Levee failure nearby Stadldorf during Danube flood 1988 – initial breachign stage, Source: WWA Deggendorf



Levee defence works carried out by soldiers during Oder flood 1997 (Source: www.planet-wissen.de)



Flood on the Isar 2005, Beaver caves, Source: WWA Freising (from Kleber-Lerchbaumer, 2010)



Elbe Flood 2013 – Levee failure near the village Fischbeck, Source: Jüpner (2016)

Outline

Introduction

General aspects

German conditions


Selected German case studies – lessons learned

Conclusion

General aspects

General requirements and challenges

- General requirements
 - Levees have to be designed, constructed, maintained and operated so that their **stability and serviceability** are always given.
 - Flood protection works do always have **priority** over all other uses and requirements; usually compromises need to be established without degradation of safety aspects (stability, defense, supervision, maintenance, access...)
 - **Nature and environmental requirements** need always to be considered and all measures have to be taken to avoid, reduce and compensate interferences.
 - Challenges
 - **Climate change** → Impact on loads (hydraulic load) and impact on structure
 - **Ageing** of structures → The smaller the structure, the “harder” the ageing effects → levees are frequently relative small structures → long-term perspective
 - **Knowledge management** → Engineering basics misremember period
 - **Long-term financing** → Flood misremember period
 -
- **Resilient and slender designs and structures**



Source:

IPCC (2021): Summary for Policymakers. In: Climate Change 2021: The Physical Science Basis. Contribution of Working Group I to the Sixth Assessment Report of the Intergovernmental Panel on Climate Change Working Group I contribution to the Sixth Assessment Report of the Intergovernmental Panel on Climate Change (IPCC), Cambridge University Press.

Legend:

SSPx-y: Shared Socio-Economic Pathway
 x: Number SSP
 y: Level of radiative forcing (in W/m²)

General aspects

Causes and reasons for levee incidents, damages and failures

- Outdated hydrological and hydraulic conditions → inadequate water levels
 - Environmental impacts (animals, woods – roots) on levee body and underground
 - Upcoming of inadequate vegetations (large trees)
 - Inadequate design and construction works
 - Inadequate structural adaptations and works
 - Ageing of materials
 - Changes of underground conditions
 - Inadequate maintenance
 -
- **Intensification** by climate change effects

Levee failure on river Loisach (Loisach) after 1999 flood in Bavaria
(Source: WWA Weilheim)



Levee failure on river Ammer after flood 1999 in Bavaria
(Source: WWA Weilheim)



Outline

Introduction

General aspects

German conditions




Selected German case studies – lessons learned

Conclusion

German conditions

Basins, hydrology, hydraulics and levees

- The huge catchments drain via first degree rivers
 - Danube
 - Rhine
 - Weser
 - Elbe
 - Ems
 - Oder
- Annual precipitation ranges from 500 to 1,000 mm/a on average for complete Germany, peaks in the Alps in the south, lows North-East.
- Trend of precipitation is positive, but anomalies are negative during the last decade → Droughts (and floods)




German conditions

Basins, hydrology, hydraulics and levees


- **Floods** are not longer dominated by long-lasting continental rains **exclusively** and snow melt but also by stormwater events (flash floods) such as occurred in 2021.
- Uncertainty of the design principles and criteria is increasing → **resilient levees** need to be designed which also reduce the residual risks and extreme load cases.




Hochwasser im Ahrtal - Historische Betrachtung und die Flut 2021 Dr. Thomas Roggenkamp Geographisches Institut Universität Bonn



CEDIM (2021): Hochwasser Mitteleuropa, Juli 2021 (Deutschland), 21. Juli 2021 – Bericht Nr. 1 „Nordrhein-Westfalen & Rheinland-Pfalz“ Forensic Disaster Analysis (FDA) Group



„Old“ standard dike section of Danube River



Standard dike section of Lower Rhine River

German conditions

Regulations, codes and standards

- DIN 19712/1997 Levees
 → **DIN 19712/2013** "Flood Protection Structures"
- DVWK 210/1986 Levees
 → **DWA M 507 Part 1** 2011 Levees
- DVWK 226/1993 (published, yellow paper)
 → **DWA M 507 Part 2** "Ecological Aspects Levees"
- DWA (2005) (under revision)
 → **DWA M 507 Part 3** "Drainage/Sealing Levees"
- BAW MSD (2011) Dams along waterways
- DIN 19700/2004 Dams ...



Outline

Introduction

General aspects

German conditions


Selected German case studies – lessons learned

Conclusion

Selected case studies – lessons learned

Old existing dikes with deficits not confirming to up-to-date regulations

- Situation
 - In consideration of actual impacts and flood incidents design fundamentals were adapted
 - For the different rivers and basins different design principles and standard sections were established
- Explanation
 - In Germany the federal states are responsible for the realization of flood protection projects
 - Although general design principles, requirements and specification are available their interpretation strongly varies
 - In addition the effects such as climate change, ageing and a lack of maintenance shows a critical impact on the performance of recommended standard designs
- Damage, deficits, threads, risks
 - Inadequate sealings (clay, thin walls...)
 - Inadequate soil materials
 - Inadequate roads incl. pavements etc.
 - Inadequate maintenance (vegetation...) ...



Standard design section developed by the WWA Deggendorf after flooding 1988 on the Danube (taken from Weiß 1997)

- Lessons learned
 - Adapt project specific designs
 - Detailed study of design variations and solutions
 - Consider long-term performance / Durability during design stage
 - Adaptation of „resilient“ designs
 - Read and understand the available codes, regulations and bulletins

Selected case studies – lessons learned

Levee failure after misleading upgrading of downstream body

- Situation
 - During a medium flood incident in 1988 at the Danube River a levee failed
 - The levee was upgrading shortly before the flood incident
- Explanation
 - The downstream slope was enlarged by placing the same soil material as used for the overall existing main dam body
 - But, modern compaction works were applied in order to compact the soil layerwise so that the relative density was higher and the permeability was lower than in the main dam body
 - Pore water pressures developed so that a geotechnical slipping failure occurred
- Damage, deficits, threads, risks
 - Complete levee failure with flooding
 - Inadequate design and construction → inhomogeneous levee section



Levee failure at the village Stadldorf during the flood 1988 on the Danube-initial stage (Source: WWA Deggendorf)

- Lessons learned
 - Rehabilitation and upgrading of levees need to comply the same requirements than a new levee
 - A geotechnical expert need to be consulted; it is not mandatory in all federal states of Germany
 - Read and understand the available codes, regulations and bulletins

Selected case studies – lessons learned

Unfavorable deformation of crest caused by inappropriate sheet piling

- Situation


- After the 1997 flooding on the Oder river ad-hoc stabilization measures were carried out
- A steel sheet pile was placed in the center of the dike body integrated only in the flood loam layer (limited depth)
- After placing the sheet pile an crest road with asphalt pavement was carried out

- Explanation

- During stability problems a center sealing was placed in order to guarantee stability upcoming floods → low costs, immediate effect

- Damage, deficits, threads, risks

- The dike body showed a low density, after further floods the deformations resulted in cracks and major deformations of the crest
- The design does not comply to techn. requirements



Rehabilitated levee section with old short sheet pile
(Source: LHW Magdeburg)



Source: Haselsteiner

- Lessons learned

- Short-termed ad-hoc measures should be always rechecked after implementation
- A combination of ad-hoc and long-term measures should be adapted
- Read and understand the available codes, regulations and bulletins

Selected case studies – lessons learned

Lost levees in upcoming forest

- Situation
 - Due to lack of floods also maintenance was lacking over years also due to poor financial resources
 - Many levee areas „vanished“ in upcoming forests
- Explanation
 - Before the 1980s serious floods were not occurring for decades
 - The importance of flood protection works was ranked subordinatedly
 - After decades those forests became nature protection areas
- Damage, deficits, threads, risks
 - All deficits and risks with large trees regarding stability, supervision and maintenance
 - Realization of flood protection or levee rehabilitation project difficult if special nature protection zones or protected species are present

Wooded levee at the River Danube nearby
(Source: StUGV)



Wooded levee at the River Iller nearby
Altenstadt (Source: TUM)



- Lessons learned
 - Levees are technical flood protection structure which require strict supervision and maintenance
 - Forests and large trees contradict all requirements of a flood protection structure
 - Read and understand the available codes, regulations and bulletins

Selected case studies – lessons learned

Pipe failure at a Lower Rhine Dike

- Situation
 - In January 2023 a sink hole occurred within a dike at the Lower Rhine which was constructed some years ago
 - The sink hole developed over night and ad-hoc safety measures were initiated
- Explanation
 - A wastewater pressure pipe leaked and transported soil material from the underground so that a sink hole occurred on the surface
 - The operation of the pumping station was stopped and within a few days the pipe section was replaced and the construction pit was refilled
- Damage, deficits, threads, risks
 - The pipe is located under or near the Rhine levee which does not comply to regulations
 - No protection pipe was applied → The pipe failure caused critical erosion
 - The refilling of the pit was not done according to regulations



- Lessons learned
 - For new levees also old existing structures should be adapted, or as here shifted and replaced
 - A adequate emergency action plan should be available which also dictates the integration of expert knowledge in emergency situations
 - Read and understand the available codes, regulations and bulletins → Clear regulations for refilling were not given

Selected case studies – lessons learned

Erosion of levee caused by bridge scour

- Situation

- During a medium flood incident in June 2023 a scour occurred a railway bridge of the Emscher River
- The bridge suffered serious deformation
- The adjacent levee suffered considerable erosion of the upstream slope

- Explanation

- Flow concentration at a bridge section of the Emscher River resulted in high velocities and scouring
- The scouring/erosion impacted a few hundred meters of the levee
- A complete failure did not occur thanks to the short flood period

- Damage, deficits, threads, risks

- Complete erosion of the upstream levee body
- The risk of breaching was critical



Source:
<https://www1.wdr.de/nachrichten/ruhrgebiet/emscherdeich-dinslaken-bruch-droht-100.html>

- Lessons learned

- Special structures within a levee always represent a risk
- Damages on these structures may extend to the levee
- Structures within a levee/river should consider flood protection safety level
- Read and understand the available codes, regulations and bulletins

Outline

Introduction

General aspects

German conditions

Selected German case studies – lessons learned

Conclusion

Conclusion

Flood protection and levee rehabilitation is a Sisyphus work

- **Resilient and slender designs and structures** meet all requirements best in consideration of future challenges such as climate change and ageing.
- An **open-minded culture** of failure is required paired with the personal and overall will of improvement as part of knowledge management.
- The importance of flood protection needs to be emphasized by **lively „lobby“ work** on all fields. This supports the financing issue.

„An Optimist is a human being, who consider the things not so tragic as they actually are.“

Karl Valentin (* 4. Juni 1882 in Munich; † 9. Februar 1948 in Planegg) German comedian, folksinger, author and movie maker.




“The struggle itself toward the heights is enough to fill a man’s heart. One must imagine Sisyphus happy.”

Albert Camus (7 November 1913 – 4 January 1960) French philosopher, author, dramatist, journalist, and political activist.



„The solution is always simple,
you just have to find it.“

Alexander Issajewitsch Solschenizyn (1918-2008),
Russian writer and noble prize winner



European Club of ICOLD
Working group on Levees and Flood Defences
EUCOLD LFD WG

Lessons learned from levee incidents and failures of German case studies

M. Sc. Burcu Ersoy, M. Sc. Lucas Werner, Dr.-Ing. Ronald Haselsteiner

The End